Cyngor Tref Caereinion Llanfair Llanfair Caereinion Town Council

WEEKLY INSPECTION SHEETS

DATED	23 rd February 2024	INSPECTION BY	R A ROBINSON
-------	--------------------------------	---------------	--------------

NO	LOCATION	ITEM	CHECKED	NOTES
1.1	MOUNT FIELD	High fences - Mount Road end	Х	
1.2		High fences – far end	Х	New fence posts being arranged.
1.3		General fences	Х	
1.4		Paths	Х	
1.5		Car park area	Х	
1.6		Containers	Х	
1.7		Railings around football pitch	Х	
1.8		Football pitch surface	Х	
1.9		Football goal posts	Х	
1.10		Hedges	Х	
1.11		Buildings (clubhouse/changing)	Х	
1.12		Stands	Х	
1.13		Signage	Х	
1.14		Litter bins	Х	Liners checked
1.15		Other items	Х	
2.1	PLAYGROUND	Fences, hedges & gates	Х	
2.2		Paths	Х	

	Grass surfaces	Х	
	Retaining posts	Х	
	Slide including steps & surface	Х	
	Junior swings and surface	Х	
	Infant swings and surface	Х	
	Roundabout unit & surfaces	Х	
	Climbing frame and surfaces	Х	
	Bouncers and surfaces	Х	
	Seats	Х	
	Signage	Х	
	Other items	Х	
PARC Y ONNEN	Grass cutting surfaces	Х	
	Gates	Х	
	Ramp into site	Х	
	Other items	Х	
CHAPEL OF REST	Building external	Х	
	Building internal	Х	
	Fire risk assessment	Х	
	Fire equipment	Х	
	Asbestos Report in place	Х	
	Electrical certificate	Х	
	Refrigeration unit	Х	
	Gardens	Х	
	Paths	Х	
	Fences	Х	
		Retaining postsRetaining postsSlide including steps & surfaceJunior swings and surfaceInfant swings and surfaceRoundabout unit & surfacesClimbing frame and surfacesBouncers and surfacesSeatsSignageOther itemsPARC Y ONNENGatesCHAPEL OF RESTBuilding internalFire risk assessmentFire equipmentAsbestos Report in placeElectrical certificateRefrigeration unitGardensPaths	Retaining postsXRetaining postsXSlide including steps & surfaceXJunior swings and surfaceXInfant swings and surfaceXRoundabout unit & surfacesXClimbing frame and surfacesXBouncers and surfacesXSeatsXSignageXOther itemsXPARC Y ONNENGrass cutting surfacesXGatesXCHAPEL OF RESTBuilding internalXFire risk assessmentXFire equipmentXAsbestos Report in placeXGardensXRefrigeration unitXPathsX

4.11		Signage	Х				
4.12		Other items	Х				
5.1	ERW DDWR	Grassed areas	Х				
5.2		Gravestones	Х				
5.3		Hedges and fences	Х				
5.4		Trees	Х	Tree report received. Estimate for works requested.			
5.5		Paths	Х				
5.6		Gates and entrance area	Х				
5.7		Signage	Х				
5.8		Rubbish area	Х				
5.9		Other items	Х				
6.1	ST MARYS CHURCHYARD	Church flood lighting	Х				
6.2		Standard lamp	Х				
6.3		Grassed areas	Х				
6.4		Trees	Х				
6.5		Boundary wall High Street	Х				
6.6		Boundary wall Broad Street	Х				
6.7		Boundary wall back of Institute	Х				
6.8		Gates	Х				
6.9		Gravestones	Х				
6.10		Signage	Х				
6.11		Paths	Х	Contractor quotes gained.			
6.12		Railings	Х				
6.13		Other items	Х				
6.14		Electrical boxes to Broad Street	Х				
	1	1					

6.15		Flags & poles main street	Х	
6.16		Other	Х	
7.1	TOILETS	Building exterior	Х	
7.2		Building interior ladies	Х	
7.3		Building interior gents	Х	
7.4		Building interior disabled	Х	
7.5		Heating units	Х	
7.6		Paths	Х	
7.7		Railings	Х	
7.8		Asbestos Report in place	Х	
7.9		Electrical certificate	Х	
7.10		Fire risk assessment	Х	
7.11		Other items	Х	
8.1	BOWLING GREEN	Buildings	Х	Club responsibility
8.2		Hedges and boundaries	Х	Club responsibility.
8.3		Greens	Х	Club responsibility.
9.1	TENNIS COURTS	Fences and boundaries	Х	
9.2		Seating	Х	
9.3		Signage	Х	
9.4		Playing surfaces	Х	
9.5		Nets	Х	
9.6		Posts for nets	X	
9.7		Hedges	Х	
10.1	STREET SCENE FIXTURES	Benches	Х	Two benches on main road need painting. Contractor instructed.

10.2		Finger posts	X	
10.3		Railings	X	
10.4		Signage	Х	
10.5		Litter bins	Х	One located on main road needs painting. Contractor instructed.
		Other items	X	
11.1	WAR MEMORIAL	Structure	X	
11.2		Railings	X	
11.3		Lights	X	
11.4		Other items	X	
12.1	DERI WOODS/GOAT FIELD	Paths	Х	
12.2		Bridges	X	
12.3		Steps	X	
12.4		Seats and benches	x	
12.5		Trees	X	
12.6		Pump House	X	
12.7		Signage	X	
12.8		Children's play pen area	X	
12.9		Dog bag dispensers	X	Checked.
12.10		Other items	X	
13.1	COUNCIL OFFICES	Internal structure	Х	
13.2		Equipment	Х	
13.3		Furniture and fittings	Х	
13.4		Notice board	Х	
13.5		Building certificates	X	The Institute is responsible for this.

13.6		Building risk assessments	Х	The Institute is responsible for this.
13.7		Fire documents	х	The Institute is responsible for this.
13.8		Risk assessment up to date	Х	
14.1	TOWN TRAIL	Sculpture and stone	Х	
14.2		Info Board by railway station	Х	
14.3		Info Board bottom of Broad Street	X	
14.4		iInfo Board in St Marys Churchyard	x	
14.5		Info Board Deri Woods	Х	
14.6		Booklet dispensers	Х	
14.7		Astley stand	Х	
14.8		Other items	Х	
15.1	TELEPHONE BOX HIGH STREET	Structure	Х	
15.2		Internal fittings	Х	
15.3		Electrics	Х	
15.4		Other items	Х	
16.1	TELEPHONE BOX W STREET	Structure	Х	
16.2		Internal fittings	Х	
16.3		Electrics	Х	
16.4		Other items	Х	
17	DEFIBRILLATORS	Watergate Street Unit	Х	Report online completed
17.1		High Street Unit	Х	Report online completed.
17.2		Mount Field Unit	Х	Report online completed.
		Rhiweniath village hall	Х	New unit to be installed at the community centre.
17.3		Institute	Х	Report online completed

17.4		Training days	Х	Completed.
17.5	Weather	Storm damage	Х	Nothing to report.
17.6	Documents	Reviews	Х	All posted on line.
18.	Riverside Walk Banwy Estate	Path strimming	Х	