WEEKLY INSPECTION SHEETS

| DATED | Week ending 1 st July 2022 | INSPECTION BY | R A ROBINSON/Town Walk |
|-------|---------------------------------------|---------------|------------------------|
| DAILD | Week ending 1 July 2022 | INSTECTION BY | with Councillors |

| NO | LOCATION | ITEM | CHECKED | NOTES |
|------|-------------|--------------------------------|---------|--|
| 1.1 | MOUNT FIELD | High fences - Mount Road end | Х | Some work to netting required, LUTFC is arranging for this.) |
| 1.2 | | High fences – far end | Х | New fence posts being arranged by Cllr R Astley. |
| 1.3 | | General fences | Х | |
| 1.4 | | Paths | Х | |
| 1.5 | | Car park area | Х | |
| 1.6 | | Containers | Х | |
| 1.7 | | Railings around football pitch | Х | |
| 1.8 | | Football pitch surface | Х | |
| 1.9 | | Football goal posts | Х | |
| 1.10 | | Hedges | Х | |
| 1.11 | | Buildings (clubhouse/changing) | Х | |
| 1.12 | | Stands | Х | |
| 1.13 | | Signage | Х | |
| 1.14 | | Litter bins | Х | |
| 1.15 | | Other items | Х | |
| 2.1 | PLAYGROUND | Fences, hedges & gates | Х | |
| 2.2 | | Paths | Х | |

| 2.3 | | Grass surfaces | Χ | |
|------|----------------|---------------------------------|---|---|
| 2.4 | | Retaining posts | Х | Some showing signs of rot, no action required at present. |
| 2.5 | | Slide including steps & surface | Х | |
| 2.6 | | Junior swings and surface | Х | |
| 2.7 | | Infant swings and surface | Х | |
| 2.8 | | Roundabout unit & surfaces | Х | |
| 2.9 | | Climbing frame and surfaces | Х | |
| 2.10 | | Bouncers and surfaces | Х | |
| 2.11 | | Seats | Х | |
| 2.12 | | Signage | Х | |
| 2.13 | | Other items | Х | New playground ordered – contractor Wicksteed. 18 th July installation |
| 3.1 | PARC Y ONNEN | Grass cutting surfaces | Χ | |
| 3.2 | | Gates | Χ | |
| 3.3 | | Ramp into site | Χ | |
| 3.4 | | Other items | Χ | |
| 4.1 | CHAPEL OF REST | Building external | Х | Redecoration of porch required Facia board to be replaced |
| 4.2 | | Building internal | Χ | |
| 4.3 | | Fire risk assessment | Х | |
| 4.4 | | Fire equipment | Х | |
| 4.5 | | Asbestos Report in place | Х | |
| 4.6 | | Electrical certificate | Х | New fuse board required and on order |
| 4.7 | | Refrigeration unit | Х | |
| 4.8 | | Gardens | Х | Hedge to be trimmed |
| 4.9 | | Paths | Х | Moss to be removed |

| 4.10 | | Fences | Χ | |
|------|---------------------|---------------------------------|---|---|
| 4.11 | | Signage | Х | |
| 4.12 | | Other items | Х | |
| 5.1 | ERW DDWR | Grassed areas | Х | New paths plan agreed for new graves area. |
| 5.2 | | Gravestones | Х | |
| 5.3 | | Hedges and fences | Х | |
| 5.4 | | Trees | Х | Trimming to be completed to all trees |
| 5.5 | | Paths | Х | Moss growth to be removed |
| 5.6 | | Gates and entrance area | Х | |
| 5.7 | | Signage | Х | Repair to entrance signage required. Instructions given. |
| 5.8 | | Rubbish area | Х | |
| 5.9 | | Other items | Х | |
| 6.1 | ST MARYS CHURCHYARD | Church flood lighting | Х | Light switch on time altered |
| 6.2 | | Standard lamp | Х | Damaged, made safe, parts now in, should be repaired soon. |
| 6.3 | | Grassed areas | Х | |
| 6.4 | | Trees | Х | Dead tree at lower end of graveyard to be removed |
| 6.5 | | Boundary wall High Street | Х | Repointing required in New Year. Report scheduled for when weather gets better. |
| 6.6 | | Boundary wall Broad Street | Х | |
| 6.7 | | Boundary wall back of Institute | Х | Quotes for retaining wall being sourced- contractor approached, awaiting quote. |
| 6.8 | | Gates | Х | |
| 6.9 | | Gravestones | Х | |
| 6.10 | | Signage | Х | No dogs signs to be put at all etrances |
| 6.11 | | Paths | Х | Some wear and tear but nothing serious. |
| 6.12 | | Railings | Х | |

| 6.13 | | Other items | Χ | Lychgate timers out for quote to repair. |
|------|-----------------------|----------------------------------|---|---|
| 6.14 | | Electrical boxes to Broad Street | Х | |
| 6.15 | | Flags & poles main street | Х | |
| 7.1 | TOILETS | Building exterior | Х | Painting of disabled unit and doors to be considered. |
| 7.2 | | Building interior ladies | Х | |
| 7.3 | | Building interior gents | Х | |
| 7.4 | | Building interior disabled | Χ | |
| 7.5 | | Heating units | Χ | |
| 7.6 | | Paths | Х | Moss growth to be removed |
| 7.7 | | Railings | Х | |
| 7.8 | | Asbestos Report in place | Х | |
| 7.9 | | Electrical certificate | Х | Electrical certificate work completed. |
| 7.10 | | Fire risk assessment | Х | |
| 7.11 | | Other items | Х | |
| 8.1 | BOWLING GREEN | Buildlings | Х | Club responsibility |
| 8.2 | | Hedges and boundaries | Х | Club responsibility. |
| 8.3 | | Greens | Х | Club responsibility. |
| 9.1 | TENNIS COURTS | Fences and boundaries | Х | |
| 9.2 | | Seating | Х | |
| 9.3 | | Signage | Х | |
| 9.4 | | Playing surfaces | Х | |
| 9.5 | | Nets | Х | |
| 9.6 | | Posts for nets | Х | |
| 9.7 | | Hedges | Х | |
| 10.1 | STREET SCENE FIXTURES | Benches | Х | Two benches on main road need painting. Spring works. |

| 10.2 | | Finger posts | Х | |
|-------|-----------------------|--------------------------|---|--|
| 10.3 | | Railings | Х | |
| 10.4 | | Signage | Х | |
| 10.5 | | Litter bins | Х | One located on main road needs painting. Spring works. |
| 10.6 | | Other items | Х | |
| 11.1 | WAR MEMORIAL | Structure | Х | |
| 11.2 | | Railings | Х | |
| 11.3 | | Lights | Х | |
| 11.4 | | Other items | Х | |
| 12.1 | DERI WOODS/GOAT FIELD | Paths | Х | Grant received, works to lower level started. First stage completed. |
| 12.2 | | Bridges | Х | |
| 12.3 | | Steps | Х | |
| 12.4 | | Seats and benches | х | |
| 12.5 | | Trees | Х | |
| 12.6 | | Pump House | Х | Mural completed. |
| 12.7 | | Signage | Х | |
| 12.8 | | Children's play pen area | Х | |
| 12.9 | | Dog bag dispensers | Х | |
| 12.10 | | Other items | Х | |
| 13.1 | COUNCIL OFFICES | Internal structure | Х | |
| 13.2 | | Equipment | Х | |
| 13.3 | | Furniture and fittings | Х | |
| 13.4 | | Notice board | Х | Backing board damp and needs replacing. Instructions given. |
| 13.5 | | Building certificates | Х | The Institute is responsible for this. |

| 13.6 | | Building risk assessments | Х | The Institute is responsible for this. |
|------|---------------------------|---------------------------------------|---|--|
| 13.7 | | Fire documents | Х | The Institute is responsible for this. |
| 13.8 | | Risk assessment up to date | Х | |
| 14.1 | TOWN TRAIL | Sculpture and stone | Х | |
| 14.2 | | Info Board by railway station | Х | |
| 14.3 | | Info Board bottom of Broad Street | Х | |
| 14.4 | | iInfo Board in St Marys Churchyard | x | |
| 14.5 | | Info Board Deri Woods | X | Instructions given to put in place on pumphouse. |
| 14.6 | | Booklet dispensers | X | Restocked. |
| 14.7 | | Astley stand | Х | Stand arrived and completed. Inatallation planned. |
| 14.8 | | Other items | Х | |
| 15.1 | TELEPHONE BOX HIGH STREET | Structure | Х | |
| 15.2 | | Internal fittings | Х | |
| 15.3 | | Electrics | Х | |
| 15.4 | | Other items | Х | |
| 16.1 | TELEPHONE BOX W STREET | Structure | Х | Paintwork to be done now external panels in place. |
| 16.2 | | Internal fittings | Х | |
| 16.3 | | Electrics | Х | |
| 16.4 | | Other items | Х | |
| 17 | DEFIBRILLATORS | Watergate Street Unit | Х | Report online completed. NHS panel completed, redecoration to be completed |
| 17.1 | | High Street Unit | X | Report online completed. |
| 17.2 | | Mount Field Unit | Х | Report online completed. |
| 17.3 | | Training days | Х | Completed. |

| 17.4 | Weather | Storm damage | Χ | None relevant this report. |
|------|-----------|--------------|---|----------------------------|
| 17.5 | Documents | Reviews | Χ | All posted on line. |